



## 7 Test Setup Photo


Radiated Emission  
Below 1GHz



Above 1GHz



## Conducted Emission



## 8 EUT Constructional Details

Reference to the test report No.: CCISE190306301

-----End of report-----