

Appendix 2 Photodocumentation

Description: Battery compartment opened

Competence Center:
Electrical & Environmental

Test report reference:
2025-AT-TC-EE-ET-EX-0-
000028-FG-018

Page: 3 of 11

Date: 09.07.2025



Appendix 2 Photodocumentation


Description: Case opened

Competence Center:
Electrical & Environmental

Test report reference:
2025-AT-TC-EE-ET-EX-0-
000028-FG-018

Page: 4 of 11

Date: 09.07.2025



Appendix 2

Photodocumentation


Description: PCB view #1

Competence Center:
Electrical & Environmental

Test report reference:
2025-AT-TC-EE-ET-EX-0-
000028-FG-018

Page: 5 of 11

Date: 09.07.2025



Appendix 2 Photodocumentation


Description: PCB view #2

Competence Center:
Electrical & Environmental

Test report reference:
2025-AT-TC-EE-ET-EX-0-
000028-FG-018

Page: 6 of 11

Date: 09.07.2025



Appendix 2 Photodocumentation


Description: RF part detail view #1

Competence Center:
Electrical & Environmental

Test report reference:
2025-AT-TC-EE-ET-EX-0-
000028-FG-018

Page: 7 of 11

Date: 09.07.2025



Appendix 2 Photodocumentation

Description: RF part detail view #2

Competence Center:
Electrical & Environmental

Test report reference:
2025-AT-TC-EE-ET-EX-0-
000028-FG-018

Page: 8 of 11

Date: 09.07.2025

