


US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor


## INTERNAL PHOTOS



**Figure 1. Unpotted Sample, Internal View**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 2. PCB assembly unmounted**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 3. Zoomed Out view of PCB assembly unmounted**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 4. PCB assembly Close Up view**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 5. PCB board 1, Side 1**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 6. PCB Board 1, Side 2**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 7. PCB Board 2 (Sensor board), Solder side**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 8. PCB Board 2 (Sensor board), Component side**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 9. PCB Board 2 (Sensor board), Component side with Shielding Removed from Transmitter circuitry**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 10. Close Up of Transmitter circuitry 1**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 11. Close Up Transmitter Circuitry 2**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 12. Inside the case**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/IC RSS Certification  
2ADWT-ICSS03  
12660A-ICSS03  
24-0101  
July 18, 2024  
Southern States, LLC  
ICS/TFDIR Sensor



**Figure 13. Inside View**