

## Annex 3: External photographs 20-1-0194901T11a-A3

|                                                         |                                                                                                                             |                        |                                       |
|---------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|------------------------|---------------------------------------|
| <b>Number of pages:</b>                                 | 8                                                                                                                           | <b>Date of Report:</b> | 2022-Jan-24                           |
| <b>Testing company:</b>                                 | CETECOM GmbH<br>Im Teelbruch 116<br>45219 Essen Germany<br>Tel. + 49 (0) 20 54 / 95 19-0<br>Fax: + 49 (0) 20 54 / 95 19-150 | <b>Applicant:</b>      | Eliko Tehnoloogia<br>Arenduskeskus OÜ |
| <b>Product:</b><br><b>Model:</b>                        | Positioning device<br>ELIKO ANCHOR                                                                                          |                        |                                       |
| <b>FCC ID:</b>                                          | 2AF2I-ANCHOR<br>(Contains FCC ID: 2AC7Z-<br>ESPWROOM32D)                                                                    | <b>IC:</b>             | --                                    |
| <b>Testing has been carried out in accordance with:</b> | CFR Title 47, Chapter I, Subchapter A<br>Part15 / Subpart F<br>§15.517                                                      |                        |                                       |

## Table of Contents

|   |                                                                |   |
|---|----------------------------------------------------------------|---|
| 1 | External photographs of Main device under test (EUT/DUT) ..... | 3 |
|   | Photograph 1 : EUT 1_Front side view .....                     | 3 |
|   | Photograph 2 : EUT 1_Rear side view .....                      | 3 |
|   | Photograph 3 : EUT 1_Left side view .....                      | 4 |
|   | Photograph 4 : EUT 1_Right side view .....                     | 4 |
|   | Photograph 5 : EUT 1_Top side view .....                       | 5 |
|   | Photograph 6 : EUT 1_Bottom side view .....                    | 5 |
| 2 | External photographs of Accessories .....                      | 6 |
|   | Photograph 1 : AE 01 .....                                     | 6 |
|   | Photograph 2 : AE 02 .....                                     | 6 |
|   | Photograph 3 : AE 03 .....                                     | 7 |
|   | Photograph 4 : AE 03 .....                                     | 7 |
|   | Photograph 5 : CAB 01 .....                                    | 8 |
|   | Photograph 6 : .....                                           | 8 |

## 1 External photographs of Main device under test (EUT/DUT)



Photograph 1: EUT 1\_Front side view



Photograph 2: EUT 1\_Rear side view



Photograph 3: EUT 1\_Left side view



Photograph 4: EUT 1\_Right side view



Photograph 5: EUT 1\_Top side view



Photograph 6: EUT 1\_Bottom side view

## 2 External photographs of Accessories



Photograph 1: AE 01



Photograph 2: AE 02



Photograph 3: AE 03



Photograph 4: AE 03



**Photograph 5: CAB 01**



**Photograph 6: RJ45 Cable (CAB02)**

**End Of Annex 3**