


6 Photographs of the Test Set-Up

Photograph 1: Set-up for Co-Located Radiated Spurious Emissions, below 1GHz



Photograph 2: Set-up for Co-Located Radiated Spurious Emissions, above 1GHz



Prüfbericht - Nr.: CN22EZX6 001
Test report no.

Seite 23 von 24
Page 23 of 24

Photograph 3: Set-up for Conducted Emissions, AC Mains

