


11th June 2019

Tosibox Lock 150 Internal Photos




Top cover from the inside




Bottom cover from the inside






PWB top view



PWB top view, RF shields removed.



PWB bottom side.