

7. Photographs of the Test Set-Up


Photograph 1: Set-up for Spurious Emissions (Front View)




Prüfbericht - Nr.: 50048435 001
Test Report No.

Seite 29 von 31
Page 29 of 31

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing

