


Appendix I PHOTOGRAPHS OF TEST SETUP


Radiated spurious emission Test Setup (Below 1GHz)- HJH124 Ble




Radiated spurious emission Test Setup(Above 1GHz)- HJH124 Ble



Radiated spurious emission Test Setup (Details)- HJH124 Ble



Radiated spurious emission Test Setup (Below 1GHz)- HJH55B Ble



Radiated spurious emission Test Setup(Above 1GHz)- HJH55B Ble



Radiated spurious emission Test Setup (Details)- HJH55B Ble



Report No. : EED39N81438802


Radiated spurious emission Test Setup (Below 1GHz)- HJSR06 Blc




Radiated spurious emission Test Setup(Above 1GHz)- HJSR06 Blc



Radiated spurious emission Test Setup (Details)- HJSR06 Ble



Radiated spurious emission Test Setup (Below 1GHz)- HJH109 Ble



Radiated spurious emission Test Setup(Above 1GHz)- HJH109 Ble



Radiated spurious emission Test Setup (Details)- HJH109 Ble



*** End of Report ***