



Appendix I PHOTOGRAPHS OF TEST SETUP


Radiated spurious emission Test Setup (Below 1GHz)- HJH158 Ble




Radiated spurious emission Test Setup(Above 1GHz)- HJH158 Ble




Radiated spurious emission Test Setup (Details)- HJH158 Ble




Radiated spurious emission Test Setup (Below 1GHz)- HJH159 Ble



Radiated spurious emission Test Setup(Above 1GHz)- HJH159 Ble



Radiated spurious emission Test Setup (Details)- HJH159 Ble



Report No. : EED39O81104002


Radiated spurious emission Test Setup (Below 1GHz)- HJSR69 Blc



Radiated spurious emission Test Setup(Above 1GHz)- HJSR69 Blc



Radiated spurious emission Test Setup (Details)- HJSR69 Ble



*** End of Report ***