Report No.:FA182305

Appendix D. SAR Test Setup Photos

Head Exposure Condition



Left Cheek, Test Separation 0 mm with front view

Left Cheek, Test Separation 0 mm with side view



Right Cheek, Test Separation 0 mm with front view

Right Cheek, Test Separation 0 mm with side view

TEL: 86-512-57900158 / FAX: 86-512-57900958

Issued Date: Oct. 13, 2021 Form version. : 200414 FCC ID: 2AJOR2101GAA Page D1 of D3

Product Specific 10g SAR



Edge1, Test Separation 0 mm

Edge2a, Test Separation 0 mm



Edge2b, Test Separation 0 mm


Edge3, Test Separation 0 mm

TEL: 86-512-57900158 / FAX: 86-512-57900958

Issued Date: Oct. 13, 2021 FCC ID: 2AJOR2101GAA Page D2 of D3 Form version. : 200414

Antenna Location

Report No. :FA182305



Note: Due to the raised camera near the antenna area, in order to get the antenna area closer to the Phantom, the camera was removed for Edge 2b, while for Edge 2a, the camera was not removed. For details, please refer to test setup photo.

TEL: 86-512-57900158 / FAX: 86-512-57900958

Issued Date: Oct. 13, 2021 Form version. : 200414 FCC ID: 2AJOR2101GAA Page D3 of D3