

























Conducted RF Spurious Emission


Condition	Mode	Frequency (MHz)	Antenna	Max Value (dBc)	Limit (dBc)	Verdict
NVNT	b	2412	Ant1	-54.07	-20	Pass
NVNT	b	2437	Ant1	-55.26	-20	Pass
NVNT	b	2462	Ant1	-54.21	-20	Pass
NVNT	g	2412	Ant1	-46.26	-20	Pass
NVNT	g	2437	Ant1	-48.68	-20	Pass
NVNT	g	2462	Ant1	-47.46	-20	Pass
NVNT	n20	2412	Ant1	-44.82	-20	Pass
NVNT	n20	2437	Ant1	-47.41	-20	Pass
NVNT	n20	2462	Ant1	-45.74	-20	Pass
NVNT	n40	2422	Ant1	-43.64	-20	Pass
NVNT	n40	2437	Ant1	-43.87	-20	Pass
NVNT	n40	2452	Ant1	-44.65	-20	Pass


























APPENDIX II - MEASUREMENT PHOTOS

Note: Please see the attached RF_Test Setup photos for FCC ID & IC.



APPENDIX III - PHOTOGRAPHS OF EUT CONSTRUCTIONAL DETAILS

Note: Please see the attached M11_External Photos and M11_Internal Photos.

※※※※※END OF THE REPORT※※※※※