



Internal Photos of EUT

Report No.: CN22PE8X 001

Model No. : roborock S7



Page: 1 of 5



Report No.: CN22PE8X 001

Model No. : roborock S7

Page: 2 of 5




Internal Photos of EUT

Report No.: CN22PE8X 001

Model No. : roborock S7

Page: 3 of 5





Internal Photos of EUT

Report No.: CN22PE8X 001

Model No. : roborock S7

Page: 4 of 5





Internal Photos of EUT

Report No.: CN22PE8X 001

Model No. : roborock S7

Page: 5 of 5



--END--