



TEST PHOTOS REPORT

Report Number. : R12373455- EP1

Applicant : Alliance Laundry Systems LLC
221 Shepard Street
PO Box 990
Ripon, WI 54971, USA

Model : 807211

FCC ID : 2ANOT-807211

IC : 23466-807211

EUT Description : Wireless Network Control

Test Standard(s) : FCC 47 CFR PART 15 SUBPART C
ISED RSS-247 ISSUE 2
ISED RSS-GEN ISSUE 5

Date Of Issue:
7 NOVEMBER 2018

Prepared by:
UL LLC
12 Laboratory Dr.
Research Triangle Park, NC 27709 U.S.A.
TEL: (919) 549-1400

REPORT REVISION HISTORY

Ver	Issue Date	Revisions	Revised By
1	9/27/2018	Initial Issue	Brian T. Kiewra
2	10/8/2018	Revised model number	Brian T. Kiewra
2	11/7/2018	Revised model number and EUT descriptor	Brian T. Kiewra

REPORT REVISION HISTORY	2
1. DESCRIPTION OF TEST SETUP	4
2. SETUP PHOTOS.....	6
END OF TEST REPORT	10

1. DESCRIPTION OF TEST SETUP

SUPPORT EQUIPMENT

Support Equipment List				
Description	Manufacturer	Model	Serial Number	FCC ID
Laptop	Lenovo	L470	PF0ZV674	N/A
DC Regulated Power Supply	CircuitSpecialists.Com	CSI3005X5	76021	N/A
Debug Device	Texas Instruments Inc.	TMDSEMU110-U	ETP_1802257	N/A


I/O CABLES

I/O Cable List						
Cable No.	Port	# of Identical Ports	Connector Type	Cable Type	Cable Length (m)	Remarks
1	DC	1	Pin	Unshielded	<3m	Connects to DC power supply
2	Debug	1	Ribbon	Unshielded	<3m	Connects to Debug device for EUT configuration

TEST SETUP

The EUT is installed in as a standalone device. Test software exercised the radio card.


SETUP DIAGRAM




2. SETUP PHOTOS

RF CONDUCTED MEASUREMENT AT ANTENNA PORT

ANTENNA PORT CONDUCTED PHOTO (FULL)





ANTENNA PORT CONDUCTED PHOTO (ZOOM)





RADIATED SPURIOUS EMISSIONS

RADIATED SPURIOUS FRONT PHOTO (Above 1GHz)



RADIATED SPURIOUS FRONT PHOTO (Below 1GHz)





RADIATED SPURIOUS EMISSIONS

RADIATED SPURIOUS PHOTO (X Orientation)



RADIATED SPURIOUS PHOTO (Y Orientation)





END OF TEST REPORT