

Photo Report on

DT RF Sensor

RF-300

FCC ID 2AO3N-TH87J6VPCS

IC: 23389-TH87J6VPCS

Test Setups

Report Reference: MDE_DEDRONE_1701_FCCb_Photo_Report

Test Laboratory:

7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Note:

The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7layers GmbH

Borsigstraße 11
40880 Ratingen, Germany
T +49 (0) 2102 749 0
F +49 (0) 2102 749 350

Geschäftsführer/

Managing Directors:

Frank Spiller
Bernhard Retka
Alexandre Norré-Oudard

Registergericht/registered:

Düsseldorf HRB 75554
USt-Id.-Nr./VAT-No. DE203159652
Steuer-Nr./TAX-No. 147/5869/0385

a Bureau Veritas
Group Company

www.7layers.com




Photo 1: Test setup for radiated measurements starting from 30 MHz




Photo 2: Test setup for conducted emissions at AC power line




Photo 3: Test setup for radiated measurements above 1 GHz