


6 Photographs of the Test Set-Up

Photograph 1: Set-up for measurement of conducted emission




Photograph 2: Set-up for measurement of radiated emission



(30-1000 MHz)

Prüfbericht - Nr.: CN23VHXX 001
Test Report No.:

Seite 36 von 38
Page 36 of 38



(1-18 GHz)