



Report No.: EED32P81900301 Page 36 of 67

9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(with adapter)(Below 1GHz)close up



Radiated spurious emission Test Setup-2(without adapter)(Below 1GHz)














Report No.: EED32P81900301 Page 37 of 67



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.

















Conducted Emissions Test Setup-1



Conducted Emissions Test Setup-2 close up

