


Prüfbericht-Nr.: DE23MWM8 001
Test report No.:


Seite 1 von 2
Page 1 of 2

Photo Documentation

Test Setup Photos



Test Setup: Radiated disturbance 30M-1GHz




Test Setup: Radiated disturbance 30M-1GHz


Prüfbericht-Nr.: DE23MWM8 001
Test report No.:

Seite 2 von 2
Page 2 of 2

Photo Documentation



Test Setup: Radiated disturbance >1GHz



Test Setup: Conducted Emission on AC Power Line