

Photo Report on Test Setups

NBIOT GPS asset tracker

TRACK1100R2

Test Report Reference: MDE_SENSOL_2201_FCC_Photo_Setups

Test Laboratory:

7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Deutsche
Akkreditierungsstelle
D-PL-12140-01-01
D-PL-12140-01-02
D-PL-12140-01-03

Note:

The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7layers GmbH

Borsigstraße 11
40880 Ratingen, Germany
T +49 (0) 2102 749 0
F +49 (0) 2102 749 350

Geschäftsführer/
Managing Directors:
Sebastian Doose
Stefan Kischka
Bernhard Retka

Registergericht/registered:
Düsseldorf HRB 75554
USt-Id.-Nr./VAT-No. DE203159652
Steuer-Nr./TAX-No. 147/5869/0385

a Bureau Veritas
Group Company

www.7layers.com




Photo 1: Test setup for radiated measurements FCC15.247, below 30 MHz




Photo 2: Test setup for radiated measurements FCC15b and FCC15.247, below 1 GHz




Photo 3: Test setup for radiated measurements FCC15b, above 1 GHz



Photo 4: Test setup for radiated measurements Parts 24, 27 and FCC15.247, above 1 GHz



Photo 5: Test setup for conducted measurements FCC15.247



Photo 6: Test setup. EUT Detail, Top



Photo 7: Test setup. EUT Detail, Bottom