



SETUP PHOTOS EXHIBIT

Report Number. : R13135764-EP1

Applicant : Nurvv Limited
Thames House, 5 Church Street
Twickenham, TW1 3NJ, UK

Model : NR1 (Left and Right)

FCC ID : 2ARGD-NR1

EUT Description : Running Tracking/Monitoring/Coaching Device

Test Standard(s) : FCC 47 CFR PART 15 SUBPART C
ISED RSS-247 ISSUE 2
ISED RSS-GEN ISSUE 5

Date Of Issue:

2019-12-30

Prepared by:

UL LLC

12 Laboratory Dr.

Research Triangle Park, NC 27709 U.S.A.

TEL: (919) 549-1400



NVLAP Lab code: 200246-0

REPORT REVISION HISTORY

Rev.	Issue Date	Revisions	Revised By
--	--	Initial Issue	--

TABLE OF CONTENTS

REPORT REVISION HISTORY	2
TABLE OF CONTENTS	3
1.1. <i>DESCRIPTION OF TEST SETUP</i>	4
2. SETUP PHOTOS.....	5
2.1. <i>NR1 (Left)</i>	5
2.2. <i>NR1 (Right)</i>	10

1.1. DESCRIPTION OF TEST SETUP

SUPPORT EQUIPMENT

Support Equipment List				
Description	Manufacturer	Model	Serial Number	FCC ID
Power supply	Bose	S008AHU0500160	072381Z60770084AE	N/A
Power supply	Bose	PSA05F-050QBT1	064184Z42943910AE	N/A


I/O CABLES

I/O Cable List						
Cable No	Port	# of identical ports	Connector Type	Cable Type	Cable Length (m)	Remarks
1	USB	1	Micro-USB	USB	<3	None
2	UART	1	USB	USB	<3	For test setup only

TEST SETUP

Test software placed the radio into the necessary modes for testing.


SETUP DIAGRAMS



2. SETUP PHOTOS



2.1. NR1 (Left)

CONDUCTED MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP


RADIATED PHOTO (BELOW 1 GHz)




RADIATED PHOTO (ABOVE 1 GHz)




X-AXIS PHOTO



Y-AXIS PHOTO




Z-AXIS PHOTO





2.2. NR1 (Right)

CONDUCTED MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP


RADIATED PHOTO (BELOW 1 GHz)




RADIATED PHOTO (ABOVE 1 GHz)




X-AXIS PHOTO



Y-AXIS PHOTO



Z-AXIS PHOTO



END OF TEST REPORT