DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America



Appendix B : Photographs

Report No: 3447ERM.003 09-17-2021






Figure B1: Front view of EUT




Figure B2: Radiated Emission Setup OM#1






Figure B3: Radiated Emission Setup OM#2




Figure B4: High range Radiated Emission Test Setup






Figure B5: Conducted Emission Test setup Front



Figure B6: Conducted Emission Test Setup Rear