


Annex B Test Setup Photos


EUT Antenna Locations






REPORT No.: SZ23060064S01


Left ear




Front Side (Test distance: 0mm)




Back Side (Test distance: 0mm)




Left Side (Test distance: 0mm)



Right Side (Test distance: 0mm)




Top Side (Test distance: 0mm)




Bottom Side (Test distance: 0mm)


Right ear




Front Side (Test distance: 0mm)




Back Side (Test distance: 0mm)




Left Side (Test distance: 0mm)



Right Side (Test distance: 0mm)



Top Side (Test distance: 0mm)



Bottom Side (Test distance: 0mm)