


Annex 2: Set-up photographs to
TEST REPORT
No.: 19-1-0002901T03a


For

PPA15 GmbH
Stollbergstr. 22
80539 München (Germany)

Cash Point Interface
sensalytics taprbox



Photograph 1: Mains conducted emission measurements test set-up for measurement of frequency up to 30MHz



Photograph 2: Radiated emission measurements test set-up for measurement of frequency up to 1000 MHz
Front side view



Photograph 3: Radiated emission measurements test set-up for measurement of frequency up to 7 GHz
Front side view