


APPENDIX 1 PHOTOGRAPHS OF TEST SETUP

Conducted spurious emission Test Setup-1



Radiated spurious emission Test Setup-2 (Below 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz)



Report No. : EED39M00060002

APPENDIX 2 PHOTOGRAPHS OF EUT CONSTRUCTIONAL DETAILS

Refer to Report No. EED39M00060001 for EUT external and internal photos.

The testing data and results in this report are just for scientific research, education, internal quality control and product development etc.

*** End of Report ***

The test report is effective only with both signature and specialized stamp; the result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.