





1.3 Photos – Test Setup




Radiated Setup < 1 GHz – View C



Radiated Setup > 1 GHz – View A



Radiated Setup > 1 GHz – View B



Test Report No.: G0M-2301-1843-TFC231PT-V02

Eurofins Product Service GmbH
Storkower Str. 38c, D-15526 Reichenwalde, Germany