



Report No.: EED32Q81046101 Page 36 of 45

## **8 PHOTOGRAPHS OF TEST SETUP**



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32Q81046101 Page 37 of 45



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 









