


Report No.: EED32P81139601 Page 34 of 48

10 PHOTOGRAPHS OF EUT Constructional Details



View of Product-1




View of Product-2

Hotline:400-6788-333 www.cti-cert.com E-mail:info@cti-cert.com



Report No.: EED32P81139601





View of Product-3










Complaint call:0755-33681700









Report No.: EED32P81139601





View of Product-5



View of Product-6













Report No.: EED32P81139601





View of Product-7



View of Product-8














Report No.: EED32P81139601 Page 38 of 48



View of Product-9



View of Product-10














Report No.: EED32P81139601 Page 39 of 48



View of Product-11



View of Product-14(adaptor 1)














Report No.: EED32P81139601 Page 40 of 48



View of Product-15(adaptor 2)



View of Product-16(adaptor 3)














Report No.: EED32P81139601 Page 41 of 48



View of Product-17(adaptor 4)



View of Product-18(adaptor 5)















Report No.: EED32P81139601 Page 42 of 48



View of Product-19(adaptor 6)



View of Product-20(adaptor 7)













Report No.: EED32P81139601 Page 43 of 48



View of Product-21(adaptor 8)

