


Photo Documentation

Test setup photos:



Picture 1: Radiated disturbance 30M-1GHz



Picture 2: Radiated disturbance 30M-1GHz

Photo Documentation




Picture 3: Radiated disturbance 30M-1GHz



Picture 4: Radiated disturbance 30M-1GHz (see test protocol 52, test with alternative setup just for information)

Photo Documentation



Picture 5: Radiated disturbance >1GHz



Picture 6: Radiated disturbance >1GHz

Anhang zu Prüfbericht-Nr.: DE23RSSK 001
Appendix to test report No.:

Seite 4 von 4
Page 4 of 4

Photo Documentation



Picture 7: Conducted voltage emissions on AC Supply line

Date Author
2024-02-09 Hümmer