



Report No.: EED32R80053301 Page 36 of 50

## **8 PHOTOGRAPHS OF TEST SETUP**



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32R80053301 Page 37 of 50



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 









