






Internal Photos of the EUT



K8204-W




ANT














6124NM







ANT

















The image shows the rear panel of a Dell monitor. On the left, there is a warning label with the text: "CAUTION RISK OF ELECTRIC SHOCK DO NOT OPEN", "FCC CE", "RoHS", "AVOID THE RISK OF ELECTRICAL SHOCK. DO NOT OPEN COVER. NO USER-SERVICEABLE PARTS. REFER SERVICING TO QUALIFIED PERSONNEL.", and "RECENT FIRE OF SHOCK HAZARD DO NOT REPAIR UNITS NOT SPECIFICALLY DESIGNED FOR OUTDOOR USE TO RAIN OR MOISTURE." To the right of the label are several ports: an A-OUT port, an HD-OUT port, a VGA port, a LAN port, a USB MOUSE port, and a USB 3.0 port. The monitor is resting on a blue surface.






ANT















87704




ANT














D214








ANT













8104









ANT











86604



ANT

