

Annex 5 Test Setup Photographs

Photo No. 22: radiated spurious



Photo No. 23: radiated spurious



Photo No. 24: radiated spurious



Photo No. 25: radiated spurious




Photo No. 26: AC conducted spurious



Photo No. 27: AC conducted spurious



Photo No. 28: tests under extreme temperature




Photo No. 29: conducted RF tests




Photo No. 30: conducted RF tests




Photo No. 31: conducted RF tests, wanted signal




Photo No. 32: conducted RF tests with LPF




Photo No. 33: conducted RF tests with stubtuner




Photo No. 34: conducted RF tests with HPF




Photo No. 35: conducted RF tests with HPF




Photo No. 36: filters externally provided



Photo No. 37: filters externally provided (e.g. applicant)



Photo No. 38: filters externally provided



Photo No. 39: attenuator/load provided by applicant




Photo No. 40: attenuator/load provided by applicant



Photo No. 41: attenuator/load provided by applicant



Photo No. 42: AC/AC converter/transformer 115 / 230 V AC used for testing



Photo No. 43: AC/AC converter/transformer 115 / 230 V AC used for testing



End of Test Report
