

Test Setup Photos



Product : The MV cable condition monitor, brand DNV
Model SCG3
Applicant: Neways Technologies B.V.

Pages : 1-5

This report is issued by Kiwa Nederland B.V, Wilmersdorf 50, 7327AC Apeldoorn, Netherlands.



Table of Contents

1. TEST SETUP PHOTOS3

1.1 Radiated emissions measurement 9 kHz – 30 MHz3

1.2 Radiated emissions measurement 30 – 250 MHz.....3

1.3 Radiated emissions measurement 250 – 1000 MHz.....3


1.4 Radiated emissions measurement 1 – 18 GHz4

1.5 Radiated emissions measurement 18 - 26 GHz.....4


1.6 Conducted emissions measurement 0.15 – 30 MHz.....5

1. Test Setup Photos

1.1 Radiated emissions measurement 9 kHz – 30 MHz




1.2 Radiated emissions measurement 30 – 250 MHz



1.3 Radiated emissions measurement 250 – 1000 MHz



1.4 Radiated emissions measurement 1 – 18 GHz



1.5 Radiated emissions measurement 18 - 26 GHz



1.6 Conducted emissions measurement 0.15 – 30 MHz

