



APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission


Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report