

APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission



Photo 1




Photo 2

Radiated Spurious Emission




Photo 1






Photo 2

Worst Case Position


6 deg



20 deg



34 deg



Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report