



Highest	7362	-55.70	-40	-15.70	-54.49	-65.16	1.92	11.38	H
	11043	-52.08	-40	-12.08	-55.5	-60.41	2.22	10.55	H
	14724	-48.63	-40	-8.63	-57.71	-58.63	2.59	12.59	H
	18399	-61.99	-40	-21.99	-73.78	-76.35	3.24	17.60	H
	22086	-61.61	-40	-21.61	-77.18	-76.98	3.52	18.88	H
	25770	-58.54	-40	-18.54	-77.2	-73.71	3.88	19.05	H
	7362	-55.51	-40	-15.51	-54.45	-64.97	1.92	11.38	V
	11043	-52.50	-40	-12.50	-55.85	-60.83	2.22	10.55	V
	14724	-47.65	-40	-7.65	-57.69	-57.65	2.59	12.59	V
	18399	-62.16	-40	-22.16	-73.71	-76.52	3.24	17.60	V
	22086	-62.14	-40	-22.14	-77.32	-77.51	3.52	18.88	V
	25770	-58.84	-40	-18.84	-77.21	-74.01	3.88	19.05	V

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



<ASDIV Antenna>

<Ant. 7>

LTE Band 48

LTE Band 48 / 20MHz / QPSK									
Channel	Frequency (MHz)	EIRP (dBm)	Limit (dBm)	Margin (dB)	SPA Reading (dBm)	S.G. Power (dBm)	TX Cable loss (dB)	TX Antenna Gain (dBi)	Polarization (H/V)
Lowest	7102	-57.60	-40	-17.60	-55.72	-67.30	1.84	11.55	H
	10653	-50.98	-40	-10.98	-53.58	-59.45	2.23	10.71	H
	14204	-49.44	-40	-9.44	-58.17	-59.07	2.65	12.28	H
	21307	-62.63	-40	-22.63	-77	-77.48	3.32	18.17	H
	24859	-59.02	-40	-19.02	-77.3	-73.79	3.71	18.48	H
	28408	-55.86	-40	-15.86	-76.37	-71.33	3.99	19.46	H
	7102	-56.84	-40	-16.84	-55.21	-66.54	1.84	11.55	V
	10653	-47.31	-40	-7.31	-49.5	-55.78	2.23	10.71	V
	14204	-49.46	-40	-9.46	-58.06	-59.09	2.65	12.28	V
	21307	-62.66	-40	-22.66	-76.72	-77.51	3.32	18.17	V
	24857	-59.18	-40	-19.18	-77.14	-73.95	3.71	18.49	V
	28408	-55.63	-40	-15.63	-75.73	-71.10	3.99	19.46	V
Middle	7230	-57.32	-40	-17.32	-55.79	-66.78	1.86	11.32	H
	10850	-50.57	-40	-10.57	-53.56	-58.94	2.22	10.59	H
	14462	-49.02	-40	-9.02	-57.99	-58.52	2.62	12.12	H
	18077	-60.33	-40	-20.33	-71.8	-74.70	3.23	17.60	H
	21696	-61.16	-40	-21.16	-76.32	-76.33	3.42	18.60	H
	25312	-58.84	-40	-18.84	-77.16	-73.84	3.77	18.77	H
	7230	-55.06	-40	-15.06	-53.88	-64.52	1.86	11.32	V
	10850	-46.77	-40	-6.77	-49.54	-55.14	2.22	10.59	V
	14462	-48.71	-40	-8.71	-58.11	-58.21	2.62	12.12	V
	18080	-60.69	-40	-20.69	-71.87	-75.06	3.23	17.60	V
	21696	-60.99	-40	-20.99	-75.81	-76.16	3.42	18.60	V
	25312	-59.17	-40	-19.17	-77.2	-74.17	3.77	18.77	V



Highest	7362	-55.30	-40	-15.30	-54.09	-64.76	1.92	11.38	H
	11043	-51.05	-40	-11.05	-54.47	-59.38	2.22	10.55	H
	14724	-48.78	-40	-8.78	-57.86	-58.78	2.59	12.59	H
	18399	-61.86	-40	-21.86	-73.65	-76.22	3.24	17.60	H
	22086	-61.58	-40	-21.58	-77.15	-76.95	3.52	18.88	H
	25770	-58.63	-40	-18.63	-77.29	-73.80	3.88	19.05	H
	7362	-54.32	-40	-14.32	-53.26	-63.78	1.92	11.38	V
	11043	-47.63	-40	-7.63	-50.98	-55.96	2.22	10.55	V
	14724	-47.94	-40	-7.94	-57.98	-57.94	2.59	12.59	V
	18399	-62.26	-40	-22.26	-73.81	-76.62	3.24	17.60	V
	22086	-62.28	-40	-22.28	-77.46	-77.65	3.52	18.88	V
	25770	-58.87	-40	-18.87	-77.24	-74.04	3.88	19.05	V

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

————THE END————