

INTERTEK TESTING SERVICE


Report No: HK12020934-1

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)

Model : 08903



INTERTEK TESTING SERVICE

Report No: HK12020934-1

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)

Model : 08903



INTERTEK TESTING SERVICE

Report No: HK12020934-1

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)

Model : 08903

