


Prüfbericht - Nr.: 12604528 003
Test Report No.:

Seite 58 von 61
Page 58 of 61

9. Photographs of test setup

Photograph 1: Set-up for Radiated Emission, EUT Configuration, Y axis



Prüfbericht - Nr.: 12604528 003
Test Report No.:

Seite 59 von 61
Page 59 of 61

Photograph 2: Set-up for Radiated Emission, EUT Configuration, X axis

