



APPENDIX 3: Photographs of test setup


Radiated Spurious Emission




Front (Below 1 GHz)



Front (Above 1 GHz)



Rear (Below 1 GHz)



Rear (Above 1 GHz)

Worst Case Position



X-axis



Y-axis



Z-axis

End of Report