



6. Photographs of test setup


The following photographs show the arrangement of the worst case.

6.1. AC Power-line Conducted Emissions Photo(s)




6.2. Antenna-port Conducted Measurements Photo(s)






Maximum Conducted Output Power




Others



6.3. Radiated Spurious Emissions Photo(s)



<EUT Axis>



The antenna was tested with attached to supporting jig that does not affect EMC characteristic in order to place for each axis.

<EUT Zoom>

