




**TX and RX Synthesizers Module – bottom and top views**




**TX and RX Synthesizer Boards removed from Synthesizers Module**




**TX Synthesizer Boards – top and bottom views**




**RX Synthesizer Boards – top and bottom views**




**Bottom Side of Main RF Board with Heatsink (right) removed.**





**Bottom Side of Main RF Board.**





**Power Supply Assembly as viewed from Right (RF Module) Side of unit.**




**Power Supply Asembly as viewed from Left (Digital Module) Side of unit.**





**Power Supply Assembly removed from unit**





**Other views of Power Supply Assembly**





**Power Supply Assembly with Capacitor Module detached.**





**Views of Circuit Board within Capacitor Module of Power Supply Assembly**



**Views of components within power supply module attached to heatsink.**



**Heatsinks of Power Supply Assembly removed, exposing Power Supply board.**





**Bottom and Top views of Power Supply board.**




**Rear Interconnect Module as part of LRU.**






**Rear Interconnect Module removed from LRU.**





**Other views of Rear Interconnect Module.**



**Cover and rear plate removed from Rear Interconnect Module.**





**Connector interface of the Rear Interconnect Module.**



**Front Panel Assembly as part of LRU (exterior front and interior views).**





**Front Panel Assembly with PCMCI card slot and RS232 covers removed,  
and then the Front panel assembly removed from LRU chassis.**



**Front Panel Assembly and circuit card.**



## Remaining Chassis when all assemblies have been removed



**Remaining Chassis when all assemblies have been removed**