

Fig. 5

Shows top side view of appliance with outer enclosure removed., and shows upper waveguide location.




Fig. 6

Shows bottom side view of oven with disassembled condition, and shows lower waveguide location.




Fig. 7

Shows rear side view of appliance with rear enclosure is removed, and shows magnetron.




Fig. 8

Shows relay unit P.W.B. assembly.




Fig. 9

Shows back-side of relay unit PWB assembly.




Fig. 10

Shows control unit PWB assembly.




Fig. 11

Shows back-side of control unit PWB assembly.

