

Annex F. Photographs

F.1 Test Samples



Sample Back 211027-01.S08




A silver laptop is shown from a three-quarter front view. The screen is black and appears to be cracked or damaged, with a small yellow sticker on the top edge. The keyboard is black and has several keys missing or damaged. The laptop is placed on a white surface next to a black ruler. There are several yellow stickers on the laptop, including one on the bottom left of the keyboard area and one on the bottom right of the laptop body. The overall condition of the laptop suggests it is old and possibly a spare part.

F.2 Test positions

Laptop




Laptop – Side view




F.3 Antenna host platform location and adjacent edge positions relative to the body

All information (diagrams, values and dimensions) in this section was provided by the manufacturer



F.4 Phantom liquid level during measurements



End of the report

This page is intentionally left blank and marks the last page of the test report.