


APPENDIX 3: Photographs of test setup


Conducted Emission




Radiated Spurious Emission



Below 1 GHz



Above 1 GHz




Worst Case Position


X-axis



Y-axis



Z-axis



End of Report