



### **APPENDIX 3: Photographs of Test Setup**

#### **Radiated Spurious Emission**


**Front**



**Rear (Below 1 GHz)**




**Rear (Above 1 GHz)**




### **Pre-check of Worst Case Position**


**X-axis**



**Y-axis**



**Z-axis**



### Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report