

APPENDIX 3: Photographs of Test Setup

Conducted Emission



Photo 1




Photo 2


Radiated Spurious Emission



Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)


Pre-check of Worst Case Position

Without Dock


With controller
X-axis



Y-axis




Z-axis




Without controller
X-axis



Y-axis



Z-axis



With Dock



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report