

APPENDIX 3: Photographs of test setup

Conducted Emission





Photo 1




Photo 2


Radiated Spurious Emission



Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)

Pre-Check of Worst Case Position

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report