

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission


Front



Raer (Below 1 GHz)



Raer (Above 1 GHz)




Pre-Check of Worst Case Position

Without Dock


With controller
X-axis




Y-axis




Z-axis




Without controller
X-axis



Y-axis



Z-axis



With Dock



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report