

APPENDIX 3: Photographs of Test Setup

Conducted Emission



Photo 1





Photo 2


Radiated Spurious Emission



Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)

Pre-check of Worst Case Position

Without Dock


**With controller
X-axis**



Y-axis




Z-axis




**Without controller
X-axis**



Y-axis



Z-axis



With Dock



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report