




APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

below 1 GHz




above 1 GHz




Pre-check of Worst Case Position


WLAN
X-axis




BT LE
X-axis



Y-axis




Y-axis



Z-axis



Z-axis



End of Report