





APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

below 1 GHz




above 1 GHz




Pre-check of Worst Case Position

X-axis



Y-axis



Z-axis



End of Report