

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

Radiated Spurious Emission


Front (below 1GHz)




Rear (below 1GHz)



Front (above 1GHz)



Rear (above 1GHz)



Pre-check of Worst Case Position

X-axis



Y-axis



Z-axis



End of Report